

7. LINE AND GROUND CONNECTIONS SHALL BE MADE PER FIG. 2, 3, OR 4.

REMOVE STRAPS FROM TERMS 21-40 AND 22-35.

ADD TP151819 STRAP ON TERMINALS C-9 AND C-11 FOR RECEIVE ONLY SERVICE AND STRAP KO-K1 ON 288 BASE.

THE A & B LEAGS SHALL BE CONNECTED TO TERMINALS ON MAYE SHAPING SET AS SPECIFIED ON THE LT WIRING PLAN (SEE BSP P30.620).